


FIG. 2

Tmeasure
At Comparator

Treceive = Tmeasure + Tdelay

FIG. 3






FIG. 5